DAILY WATER SUPPLY SYSTEM STATUS UPDATES

Water supply status update by exception (i.e., areas affected due to supply constraint and not service interruption from occasional pipe burst). Tuesday, 2 April 2024 (Afternoon)

UNPLANNED MAINTENANCE

Update on repairs in Central Region

The draining of water has been completed and the team will install a clamp around the leaking section. Welding has been completed at corner Golf Avenue and Republic Road.

Suburbs Affected: Cresta; Windsor East; Windsor West; Windsor Glen; Randpark; Robin Hills; Fontainebleau; Moret; President Ridge; Malanshof; Risidale; Blackheath; Montroux; Franklin Roosevelt Park; Linden; Aldara Park; Darrenwood; Jaganlee; Robindale; Blairgowrie; Robin Acres; Ferndale; Beverley Gardens; Brynston West Ext 1; Vandia Grove: and Bordeaux.

Street Names: All streets

Reservoirs/towers affected: Linden Reservoir 1 and towers; Linden reservoir 2; Kensington B reservoir and tower; and Blairgowrie reservoir.

Expected start date: 2 April 2024

Expected completion time: 10:00 - 20:00

Impact on customers: Low pressure to no water

Reason for disruption: Repairing of 711mm steel pipe along Corner Republic Road and Judges Avenue, as well as corner Republic Road and Golf Avenue, Cresta and Windsor East.

Alternative water supply: Will be provided as and when the need arises.

Suburbs affected: Orlando West and Dube

Street names: All streets

Reservoirs/towers affected:

Expected start date and time: 3 April 2024 at 05:00

Expected completion date and time: 4 April 2024 at 19:00

Impact on customers: No water

Reason for disruption: Repairs on 450mm burst pipe

Alternative water supply: Roaming water tankers will be provided to

affected areas.

C B E G

REGIONS

LOG A CALL



011 688 1699/ 086 056 2874



45201



Customerserviceemails @jwater.co.za



@JHBWater



Johannesburg Water



Areas affected: Woodmead Extension 40.

Street names: Woodmead Drive, Waterval Crescent, Woodlands Drive

Date: 9 April 2024

Time: 07:00 - 17:00

Impact on customers: No water

Reason for interruption: Connection of new water pipe

Alternative water supply: Further details to be provide

