



a world class African city

City of Johannesburg

Johannesburg Water SOC Ltd

Turbine Hall 65 Ntemi Piliso Street PO Box 61542 Newtown Johannesburg

Johannesburg Water Marshalltown

Tel +27(0) 11 688 1400 Fax +27(0) 11 688 1528

www.johannesburgwater.co.za

Daily water supply system status updates: Friday, 1 September 2023 (Afternoon)

Water supply status update by exception (i.e., areas affected due to supply constraint and not service interruption from occasional pipe burst).

Unplanned interruption

Johannesburg Water systems update

The following Johannesburg Water reservoirs and towers are still struggling with capacity due to poor supply and high-water demand.

South Hills tower

Critically low due to poor supply. Low pressure to no water is expected in the supply zone as the tower is currently on bypass.

Commando System

- Crosby reservoir: Remains low but supplying normally. Poor pressure is expected.
- Hursthill 1 reservoir: Critically low due to high demand and slow recovery. The network has been reconfigured to augment Hursthill 1 reservoir supply. Low pressure to no water is expected in high-lying areas.
- Hursthill 2 reservoir: Critically low to empty due to high demand and slow recovery. Low pressure in low-lying areas and no water in high-lying areas is expected. Outlet will be isolated tonight from 21:00 and opened at 05:00 on Saturday to build capacity.
- Brixton reservoir: Low but supplying normally. The demand is high; therefore, customers in low-lying areas are requested to reduce consumption.
- Brixton tower: Operating normally.

Eagles Nest reservoir

Remains critically low due to poor supply and high demand. Customers in this supply zone should still expect low water pressure.

Doornkop reservoir

Remains low, but stable. It is supplying normally.

Linden 1 tower

Operating normally.

Alternative water supply is still being provided through 14 roaming trucks deployed at various key points of the struggling areas. Johannesburg Water is monitoring the systems and will provide more information.

Planned interruptions

Ms Gugulethu Phakathi (Chairperson), Mr Ntshavheni Mukwevho (Managing Director and Executive Director), Mr Johan Koekemoer (Financial Director and Executive Director), Mr Phetole Modika, Mr Siphamandla Mnyani, Mr Siyabonga Mthembu, Mrs Zandile Meeleso, Mr Pholoso Matjele, Mr Kgaile Mogoye, Mr Molate Mashifane, Ms Pamela Mabece, Mr Lunga Bernard

Ms Kethabile Mabe (Company Secretary), Johannesburg Water SOC Ltd Registration Number: 2000/029271/30





a world class African city

City of Johannesburg

Johannesburg Water SOC Ltd

Turbine Hall 65 Ntemi Piliso Street Newtown Johannesburg Johannesburg Water PO Box 61542 Marshalltown 2107 Tel +27(0) 11 688 1400 Fax +27(0) 11 688 1528

www.iohannesburgwater.co.za

1. Suburbs Affected: Jukskei Heights Ext 3, Jukskei View Ext 18, 19, 37, 38, 43, 44, 45, 50, 51, 55 and 107

Street Names: Waterfall Drive, Appaloosa Dr, Waterfall Hills Lane, Polofields Dr, Country Estate Dr, Augrabies Falls Boulevard, Kalambo Falls Ave, Ruacana Falls, Kalandula Falls, Howick Falls, Victoria Falls, Howick Falls, Tugela Falls, Mangeni Falls, Bingini Crescent, Woodmead Dr, Polo fields Dr, Ibis Drive, Jacana Drive, Stilt Drive, Plover Drive, Egret Dr, Heron Dr, Cormorant Dr, Teal Dr, Spoonbill Drive.

Date: 5 September 2023 **Time:** 09:00 - 21:00

Impact on customers: Low pressure to no water

Reason for disruption: Relocation and tie-in of a new infrastructure

Water Tankers: Water tankers will be placed at corner Waterfall and Polo Fields Drives

2. Reservoirs/towers affected: Berea Reservoir; Hursthill Reservoir no.1 & 2; Linden Reservoir no. 1 & 2; Parktown Reservoir no. 1& 2; Dunkeld Reservoir

Suburbs Affected: De Wetshof, De Wetshof Ext 1; Observatory Ext; Oospoort Ext 1; Bruma; Cyrildene: Bezuidenhout Valley: Bertrams; Lorentzville: Judith's Paarl: Troyeville: Langlaagte: Mayfair; Homestead Park; Amalgam; Crown, Crown North; Paarlshoop; Montgomery Park & Montgomery Park Ext 3; Albertville & Albertville extensions 1, 4, 5, 6, 7, 8, 9, 10, 11, 12; Franklin Roosevelt Park & Franklin Roosevelt Park Ext 1; Westbury & Westbury extensions 2 & 3; Northcliff extensions 12, 15, 19, 20, 21, 32; Albertskroon; Greymont & Greymont Ext 1; Coronationville; Hursthill; Claremont; Newlands; Martindale; Triomf; Montclare & Montclare Ext 1; Westdene: Newclare: Delarey: Cresta ext 81: Saxonwold & Saxonwold extensions 1, 2, 3, 4, 5, 6; Hyde Park, Hyde Park A Settlement & Hyde Park extensions 8, 12, 16, 19, 21, 27, 37, 47, 49, 63, 65, 73, 80, 85, 86, 87, 94, 116, 120, 121, 122, 123, 124, 128, 130; Melrose, Melrose Estate, Melrose North & Melrose North extensions 1, 2, 3, 4, 5, 7, 9, 10; Dunkeld, Dunkeld West & Dunkeld West extensions 1, 2, 3, 4, 5, 7, 8; Parkview & Parkview Ext 1; Parktown & Parktown North; Parkwood & Parkwood Ext 1; Illovo & Illovo extensions 1, 3, 4, 7, 8, 9, 10, 11, 12; Greenside, Greenside East & Greenside extensions 2, 4, and 5; Birdhaven; Riviera; Killarney; Oaklands; Craighall, Craighall Park; Westcliff; Forest Town; Houghton Estate: Birnam: Rosebank: Fairway.

Street Names: All streets

Start date: 5 September 2023 at 15:00 **End date:** 6 September 2023 at 08:00

Impact on customers: Low pressure to no water

Reason for disruption: Replacement of the 800mm Stafford meter along Rand Water bulk

line supplying Johannesburg Water

Water Tankers: Water tankers will be deployed to affected areas

More information can be obtained on:

Twitter: @JHBWater / Facebook: Johannesburg Water

Website: https://www.johannesburgwater.co.za **24-hour Hotline:** 011 688 1699/ 086 056 2874

SMS line: 45201 / Email: customerserviceemails@jwater.co.za

Directors:

Ms Gugulethu Phakathi (Chairperson), Mr Ntshavheni Mukwevho (Managing Director and Executive Director),
Mr Johan Koekemoer (Financial Director and Executive Director), Mr Phetole Modika, Mr Siphamandla Mnyani, Mr Siyabonga Mthembu, Mrs
Zandile Meeleso, Mr Pholoso Matjele, Mr Kgaile Mogoye, Mr Molate Mashifane, Ms Pamela Mabece, Mr Lunga Bernard

Ms Kethabile Mabe (Company Secretary), Johannesburg Water SOC Ltd Registration Number: 2000/029271/30